



Control Plastics Inc. 377 Oyster Point Blvd #10 SSF CA 94080
800-600-2010 www.controlplastics.com sales@controlplastics.com

COMPROMISE FOR DESIGN—Achieving the optimum part design

The goal in designing a new part/product is to make the best compromise from all the factors available, You need to weigh ALL the facts and ALL the needs: The designer determines the QUALITY, the PRICING and the CONSISTENCY.

The toolmakers, and molders are stuck with the design they are handed. They can only try to optimize the situation. This design process is iterative. As you go through each section, and make a tentative decision, you need to go back to all of the prior sections to see how they have been affected.

1 PART DESIGN AND FUNCTION...Most critical is—Can it do what is needed? Did you Talk to the Customers (VOICE OF THE CUSTOMER)?, Marketing?, Sales?, Finance?, Production? They all have different needs and wants. And they are all important.

2 MATERIAL SELECTION...Plastic (thermoset or thermoplastic? Amorphous or Crystalline? Rigid or elastomeric?) Metal? Wood? Ceramic? Cloth? Where is it used----- Indoors, Outdoors? Chemical exposures? FDA requirements? UL requirements? ISO requirements? nsf requirements—and on and on----- Lots of choices, and more than one material will likely work. The process you pick will also affect the material—and vice versa. See the attached checklist to make sure you have considered all of the factors

3 PROCESS REQUIREMENTS.. How will you make it? Injection molding? (overmold?, 2 shot?, Structural foam?), Die casting? Investment casting? Sand casting? Gravity casting? Aluminum extrusion? Plastic extrusion? MIM (metal injection molding)? Blow molding? RIM (Reaction Injection Molding)?, Stamping (4 slide, progressive, deep draw)? Laser cut or NCT and bend)? Machining? Each process will require a different adjustment to the ideal functional design.

4 TOOLING DESIGN AND FUNCTION..Most processes require tooling. And the part design needs to be adjusted for the tooling requirements. Also, the desired life of the tool can affect the design requirements of the tool and the part design.

5 SECONDARY OPERATIONS, AUTOMATION, and ASSEMBLY (Ultrasonic, heat, dielectric, and mechanical) FINISHING (pad print?, silk screen?, hot stamp?, painting?, plating?) Everything you sequentially do with this part, will come back to affect the part design. They all need to be considered BEFORE you start any tooling.

6 QUALITY CONTROL and CONSISTENCY. The part needs to be readily inspected and measured. We need to go through steps of Validation and verification. The easier you make this process, the more likely it will be checked on a regular basis

7 END OF LIFE and ENVIRONMENTAL concerns. This is becoming more and more of a critical concept. And it does affect the part design, and the materials chosen to make the part from. The parts can affect the environment, just as the environment can affect the part.

8 Be Careful where you get help and information. If you go to an Architect with a problem, you will likely be given a building as a solution. You will get different "help" from Processing engineers, Assembly managers, Toolmakers, Material suppliers—et al.

COMMON ISSUES IN INJECTION MOLDING

There are some very common issues that reoccur in many parts...So we need to be concerned about the following:

INTERNAL RADII. All plastics are "notch sensitive".. Any internal corner can create a stress riser—Even if we have almost no internal stresses, this is a highly likely cause for an impact failure...

Solution: Add radiused corners at all internal corners. No problem—EXCEPT ---- larger radii will effectively increase the wall section...And we can get a sink issue. There are several guidelines about the optimum radius at the inside corners—and they hold true—up to the point of causing sink.

GATING The two weakest places on an injection molded part are the gate locations and the weld line.

The gate is the place of highest fill pressure, and hence the highest internal stresses are there. The gate location and type can also influence flatness and warp, weld lines, needed secondary operations after molding, molecular orientation of the polymer(and more)...

WELD LINE The plastic flow will separate when flowing around a core in the mold (hole, window, etc.). When it gets to the far side of the hole, the material has to meld (weld) back together... There are many reasons this area is weaker: The plastic is cooling as it flows, so the fronts of material may not fully melt back together. There can be trapped air at the weld lines—and this prevents the material from melting together (You can actually get "dieseling", or burning, when you compress trapped air).. Also, any of the fillers, or reinforcing agents (glass fiber, for instance) do not cross the weld line. They only come up to the weld line. At best, your weld line is only about 95% of the strength of the UNFILLED material.

VENTING. We all learned that only one type of matter can occupy a space, at one time. IF we want to fill a cavity with plastic, we need to get the air removed. This can be done by properly placed vent locations — which will ensure we are getting air removed at the last places to fill, as well as all along the fill path. We can even make the venting positive (vacuum venting). Improper venting severely limits the processing window, and can affect the overall strength of the part.

RIBS. When ribs intersect a wall, they give us a locally thicker area. This can be a cause of sinks. Rules of thumb are to make sure the ribs (including radii on internal corners) are no more than 50% of the wall it intersects.

BOSSES. Bosses have center core pins surrounded by plastic. The pins cannot always carry the heat away as fast as the surrounding steel—so the pin heats up. This can create sink marks. There are lots of little tricks to help alleviate the potential sink marks

SINK MARKS and SHRINKAGE. All plastic materials get smaller in volume when the solidify (transition from liquid to solid). The amount of shrinkage depends upon:

The material—Amorphous (shrink less) or Crystalline, Reinforcements (glass fibers, minerals used in the plastic

- ▣ --Flow or Cross flow directions. Flow direction usually has lower shrinkage than cross flow
- ▣ --Wall sections. Thicker parts have more shrink.
- ▣ --Mold Temperatures.

When you start to get sinks in a part, the plastic no longer contacts the mold surface...You actually create a vacuum between the plastic part and the mold cooling surfaces. The rule of thumb is to run the mold as warm as possible to still get the heat transfer needed, and achieve the desired cycle. This allows for better packing of the part.

Plastics are very good heat insulators. As parts get thicker, the cooling time goes up logarithmically . the longer a plastic stays hot, the more shrinkage it will exhibit. If the design rules are "stretched", the processor usually needs to increase packing and holding pressures, increase speeds, and cool down the material stock temperature and mold temperature (creating a compromise for surface uniformity and weld lines).

All of this creates HIGHER INTERNAL STRESSES.

HIGH INTERNAL STRESSES

Ok—You have gotten past the initial set of compromises. You have a pretty good idea of part design and have been through the first iterations of compromise.... Main remaining concern is INTERNAL STRESS LEVELS

First—What is the definition of a "good "plastic part?: It needs to look good, meet tolerances, and have LOW INTERNAL STRESS.

High internal stress gives you the following:

- ▣ Lower impact strengths
- ▣ Lower heat distortion resistance
- ▣ Lower chemical resistance
- ▣ Low dimensional stability, and warp
- ▣ Lower environmental stress cracking resistance
- ▣ Worse low temperature properties---

Not a one of these makes a better part... So what causes high internal stresses, and how do we prevent them?

In general, the harder we have to pack out an injection molded part (higher pressures, and longer holding times), the more internal stresses we build into the part... Why do we build these high internal stresses into the part? .. Most of the time, we do so to make up for bad part design....And the most common culprit is sink...

Because of the importance, I will repeat myself---. Plastics get smaller in volume when they cool from liquid to solid. This is referred to as shrinkage. Every material has a shrinkage range. The longer the material stays hot in the mold, the more shrinkage occurs... When you have details, such as ribs, bosses, improper thickness transitions (try to keep a transition distance of at least 5 times the change in thickness), they create a localized thicker area. This area takes longer to cool, so you get more shrinkage in the thicker area. This will give you a "sink". This sink can be measureable (often at the intersection of a rib to a wall), or just slight enough to cause a surface gloss difference (often at the parting line where you have a thinner wall section for the interlocks).

Customers don't like sinks or the gloss changes (even though they have caused them by their design). Molders try to accommodate by increasing injection and holding pressures, and adjusting mold temperatures. They can minimize the sinks with these tricks—but at the expense of increasing the internal stress levels

Please note the attached Checklist. This lists many of the factors you need to consider and balance, in order to make a GOOD PLASTIC PART..

This paper was intended to be a simplified overview of the many factors required in designing a good plastic part. There are a lot more details available from the many design guides from the raw material suppliers. Many of the articles/ brochures that I have found useful over the years, have been put on our web site—

PACKAGING CONSIDERATIONS

BARRIER PROPERTIES _____

H2O (WALL THICKNESS) _____

CO2 _____

NITROGEN _____

ETHYLENE OXIDE _____

GAS _____

OTHER

BIO-DEGRADATION _____

BACTERIAL/FUNGI RESISTANCE _____

OUTGASSING (Electronics+Painting Foams) _____

SPECIFIC GRAVITY (BASIC MATERIAL) _____

SPECIFIC GRAVITY (FOAM) _____

RADIATION OPACITY _____

SURFACE FEEL (Tacky, Dry, Slippery, Smooth, Rough) _____

SOUND DAMPENING _____

OPTICS

CLEAR, OPAQUE, TRANSLUCENT (THICKNESS) _____

BIREFRINGENCE _____

DIFFUSIVITY _____

REFRACTIVE INDEX (ND) _____

HAZE (AT WHAT THICKNESS) _____

TRANSMISSION (AT WHAT THICKNESS/WAVE LENGTH) _____

CRITICAL ANGLE (IE) _____

REFLECTIVITY _____

FINISH (SCRATCH / DIG) _____

APPEARANCE CHARACTERISTICS

COLOR _____

(PIGMENT/DYE/PEARLSCENT/FLUORSCENT/PHOSPHORESCENT)

FINISH (SPE=SI NUMBER/OPTICAL/TEXTURED/(MOLD TECH/EDM

BLASTED)/RMS) _____

SURFACE UNIFORMITY _____

SECONDARY OPERATIONS

DECORATING _____

MOLD SPRAY ALLOWED _____

SILK SCREEN _____

HOT STAMP _____

LABELS _____

PAINT _____

PLATE (Vacuum, Electro, Electroless) _____

FLAME SPRAY _____

ELECTROSTATIC COATING _____

FLUIDIZE BED COAT _____

BLAST/HONE _____

MECHANICAL _____

DRILLING, TAPPING, CUTTING _____

ULTRASONICS, VIBRATORY+SPIN WELDING, DIELECTRIC

HEAT STAKING _____

ADHESIVES (HOT MELTS, PRESSURE SENSITIVE, SOLVENT)

SCREWS (SELF TAP, CAPSERTS) _____

INSERTS (EXPANSION, PRESS IN, ULTRASONIC)

SNAP FITS _____

INTERFERENCE FITS _____

STRESS RELIEF / HEAT OR RADIATION CROSS LINKING / POST

MOLD ORIENTING) _____

MOLDING CONSIDERATIONS

ENCAPSULATION _____

MATERIAL SHRINKAGE+SHRINKAGE RANGE _____

TOLERANCES _____

SINK, VOIDS _____

POST MOLD SHRINKAGE & CRYSTALLIZATION _____

ORIENTATION _____

MOLDED IN STRESSES (FOAM) _____

SHEAR SENSITIVITY _____

VISCOSITY AND FLOW LENGTH _____

HEAT STABILITY _____

MOLD SPRAY _____

REGRIND ALLOWED (PROPERTY CHANGES DUE TO CROSSLINKING

OR VIS BREAKING) _____

MATERIAL CHECKLIST

EXPECTED PART LIFE _____

USE OF PART _____

LIABILITY IF FAILURE _____

ELECTRICALS

SURFACE + VOLUME RESISTANCE _____

DIELECTIC STRENGTH - SHORT TERM _____

DIELECTIC CONSTANT _____ HERTZ

DISSIPATION FACTOR _____ HERTZ

ARC RESISTANCE _____

ANTI-STATIC PROPERTIES _____

SHIELDING _____

ELECTRICAL GROUNDINGS _____

MECHANICALS

COMPRESSIVE MODULUS _____

HOURS UNDER LOAD _____

TENSILE STRENGTH _____

TENSILE/FLEXURAL MODULUS _____

ELONGATION _____

CREEP RESISTANCE _____

ABRASION/SCRATCH RESISTANCE _____

TEAR STRENGTH _____

FATIGUE RESISTANCE _____

VIBRATION TESTS _____

HINGE CAPABILITY (MOLDED IN/COINED) _____

SHEAR STRENGTH _____

COEFFICIENT OF FRICTION (STATIC/DYNAMIC) _____

HOOP STRENGTH (BURST PRESSURE) _____

IMPACT (IZOD/DROP) _____

TEMPERATURE

HIGHEST USE TEMPERATURE (LOADED/STATIC) _____

LOWEST USE TEMPERATURE (LOADED/STATIC) _____

HOURS AT HIGHEST TEMPERATURE-- LTHA _____

COEFFICIENT OF EXPANSION _____

THERMAL CONDUCTIVITY _____

MOISTURE

ENVIRONMENTAL HUMIDITY _____

WATER ABSORPTION _____

WATER ADSORPTION _____

HYDROLYSIS RESISTANCE _____

FLAMABILITY

UL 94 /746 CLASSIFICATION _____

UL HEAT DISTORTION _____

OUTDOOR EXPOSURE

U.V. (LIFE) _____

CHEMICAL _____

MOISTURE _____

CHEMICALS

EXPOSURE TIME/TEMPERATURE _____

LOAD WHEN EXPOSED _____

STRESS CRACKING RESISTANCE _____

ACIDS (STRONG/WEAK) _____

ORGANIC SOLVENTS _____

ALKALAI (STRONG/WEAK) _____

GREASES / OILS / LUBRICANTS _____

PERSPIRATION, BODY FLUIDS _____

OTHER PLASTICS _____

FOODS (FDA) _____

MEDICINES (ALCOHOLS/BLOOD) _____

COSMETICS _____

PAINTS/COATINGS/ADHESIVES/ CLEANING _____

DEIOIZED H2O _____

POTABLE WATER (NSF) _____

GREY WATER (SEWAGE) _____

Consider both the effect of the environment on the plastic and vice versa

STERILIZATION _____

GAS (ETO) / RADIATION / CHEMICAL _____

STEAM (TEMPERATURE / PRESSURE / TIME _____

RoHS, REACH, NSF,FDA , EPA _____

EN (ISO), EPA, ASTM, WEEE Specifications _____

ENVIRONMENTAL STRESS CRACKING _____

PART DESIGN CONSIDERATIONS

SPRUE (CONVENTIONAL/HOT) SIZE _____
 SPRUE PULLER (Z OR UNDERCUT) _____
 COLD SLUG WELL - (SIZE) _____
 RUNNER BAR (MATERIAL/HARDNESS) _____
 BACK-UP PLATES (1 7/8" MIN) OR INSERTS (MATERIAL HARDNESS) _____
 (BLIND-THRU) POCKETS _____
 Material hardness finish surface-treatment special Mfg.
 CAVITY INSERTS _____
 CORE IINSERTS _____
 (H-12, S-7, P-20, ALUMINUM, BE/CU, O-1, A-10, M-2, P-4)
 All hardened inserts are to be stress relieved (double drawn). When Feasible, stress relieve inserts after EDMing.
 GATES – (Round Edge, Trapezoidal Edge, Rectangular Edge, Half Round Edge, Tapered – ½ Edge, Tapered-Full Edge, Sub Gate, Thru Ej. Pin, Pin Point, Diaphragm, Flash, Fan, Ring, Pool, Tab.
 SIZE _____ LAND _____
 EJECTION – (PINS- DME – std., Pins-High Speed, Sleeves-Std/Special, Blades, Plate, Double Action, Hot-side, Cammed Ejectors, Kicking Ejectors, Spring Loaded, Multiple (via Springs & Jiffy Locks), Guided Ej. Plate (Required with All Sleeves & Pins under .062")
 PARTING LINE (Regular/Stepped) _____
 SIDE ACTIONS (With Positive Return & Full Locking) – (A-Side/B-Side, Angle Pin, Hydraulic, Air, Cam, Cammed Ejectors, Kicking Ejectors, Interlocking, Automatic Unscrewing, Collapsing Cores, Stilson Core, Hand Loaded – Core/Slide, Molded In Inserts (All HL or Molded In Inserts must fit in only one side of the mold, in only one Direction, and in only one location.
SAFETIES
 BERMER RETURN _____
 DME RETURN _____
 MICROSWITCHES _____
 SPRING LOADED EJECTION _____
 OTHER _____
COOLING
 BASE ONLY _____
 (ALL PLATES) _____
 INTO EACH CAVITY & CORE _____
 (INDIVIDUAL CONTROL) _____
 FOUNTAINS _____
 BAFFLED INNER CORES _____
 HEAT SINKS _____
 HEAT PIPES _____
RUNNERS - TYPE
 SIZE _____ (2ND) _____ (3RD) _____
 STREAMLINE/CONVENTIONAL/LAYOUT _____
VENTING
 VACUUM POPPETS _____
 VENT WELLS _____
 P/L EDGE VENTS _____
 THRU CORE/EJECTORS _____
 VACUUM EVACUATION _____
 SPARE PARTS _____



Control Plastics Inc. 377 Oyster Point Blvd #10 SSF CA 94080
 800-600-2010 www.controlplastics.com sales@controlplastics.com

WALL THICKNESS/UNIFORMITY _____
 SINK/VOID POTENTIAL (CORING) _____
 RADII ON CORNERS _____
 DRAFT _____
 REINFORCING RIBS _____
 GATING (SIZE, LOCATION) _____
 WELD LINES (STRENGTH) _____
 PARTING LINE _____
 EJECTION (PINS, BLADES, SLEEVES, PLATES) _____
 SIDE ACTIONS (A-SIDE, MECH, HYDRAULIC, EJECTORS) _____

HAND LOADED INSERTS _____
 STRESS RELIEVING/POST MOLD CROSSLINKING OR ORIENTING _____

HOW IS PART USED? _____
 WHAT HAPPENS IF IT FAILS? _____
 EXPECTED FAILURE OR REJECT MODE? _____
 WILL PROPERTY CHANGES, DUE TO AGING, CAUSE PROBLEMS? _____

FIXTURES NEEDED

COOLING _____
 TRIM _____
 Q.C. _____

Q.C. & INSPECTION REQUIREMENTS

DIMENSIONS _____
 LINEAR _____
 HOLE DIAMETER _____
 CONCENTRICITY OR T.I.R. _____
 FLATNESS (BOW/WARP) _____
 PERPENDICULARITY _____
 CRITICAL/CONTROL DIMENSION & TOLERANCE FIT AND FUNCTION REQUIREMENTS _____
 (INITIAL DIMENSIONS VS. PART TO PART UNIFORMITY) _____

APPEARANCE

GATE TRIM _____
 SINKS _____
 VOIDS/BUBBLES _____
 FLASH _____
 PARTING LINE MATCH _____
 CLARITY _____
 SCRATCHES _____
 UNIFORMITY OF SURFACE _____
 FINGER PRINTS _____
 MOLD SPRAY _____
 FLOW LINES (PIGMENT ORIENTATION) _____
 WELD LINES _____
 BLACK SPECKS _____
 BURNS _____
 SPLAY/BLUSH _____
 EJECTOR MARKS _____
 AQL LEVEL _____
 SPECIAL TESTS _____

PACKAGING

LAYERED (DIVIDERS) _____
 BULK _____
 TISSUE WRAP _____
 SEPARATE P.E. BAG _____
 FOAM PACK _____
 STACKED _____
 EGG CRATE _____
 SPECIAL TRAYS _____
 PARTS PER BOX _____
 PARTS PER BAG _____

TOOLING CHECKLIST

NUMBER OF CAVITIES _____
 MATERIAL (PLASTIC) _____
 SHRINKAGE (FLOW, CROSS, FLOW) _____
 TOOL LIFE _____
 PRESS SIZE _____
 SHOT SIZE _____
 ESTIMATED CYCLE (PARTS/HOUR) _____
 MOLD TYPE (STANDARD, HOT RUNNER, 4 PLATE, INSULATED RUNNER) _____
 MOLD SIZE (MINIMUM OF 2" AROUND CAVITIES) _____
 BASE MATERIAL (DME #1,2,3, ALUMINUM, H-13) _____